# This Page Is Inserted by IFW Operations and is not a part of the Official Record

#### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

#### IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

FIG. 1



THE TENSILE STRENGTH OF CUNISI AND CUSNNISI SINTERED MATERIALS (  $\sigma_{\mbox{\scriptsize b}}$  )





FIG. 3

THE STRUCTURES OF Cu-Ni-Si BASED SINTERED COMPACTS (A MAGNIFICATION OF ×400) (SINTERING CONDITION 1100°C×1HR)



THE STRUCTURE OF A Cu-3Ni-1Si-0.5SiO $_2$  BASED SINTERED COMPACT (A MAGNIFICATION OF ×100) (1100°C × 1HR)






FIG. 5



THE STRUCTURE OF A Cu-10Sn-10Ni-0.55FeP-3Pb (B16) BASED SINTERED COMPACT (850°C × 1HR)






FIG. 8

